

June 29, 2011

Mr. Eric Hausamann, P.E.
NYS Department of Environmental Conservation
Remedial Bureau E, Section B | Division of Environmental Remediation
625 Broadway, 12th Floor
Albany, New York 12233-7017

Re: Former Roth Bros. Smelting Corp. Site 6223 Thompson Road, Dewitt, New York Consent Order C7-0001-94-10

Consent Order C7-0001-94-10
2011 Annual Asphalt Cap Inspection

Dear Mr. Hausamann:

On June 20, 2011, Mr. Chris Laurin from Ruston Paving Company, Inc., conducted the annual inspection of the asphalt cap covering the corrective action management unit (CAMU) at the above referenced site. Results of the annual inspection are being submitted to meet the annual inspection reporting requirements. A copy of the 2011 Ruston Paving Report, which includes photographs of the existing CAMU asphalt cap and the repair areas, is attached.

The asphalt cap had some minor areas in need of repair and a few noted areas of vegetation growth along the joint between the concrete dolly apron and the asphalt. Vegetation was also observed growing along the eastern side slope but not directly on the CAMU asphalt cap. All of the vegetation was treated with a non-selective herbicide (Round-Up) then the entire area was power swept. As done previously, the asphalt repair areas were filled with a hot asphalt mix and the repair edges were sealed.

If you have any questions about the attached inspection report or any of the routine repair work performed, please do not hesitate to contact me.

Sincerely,

Deńnis Flanagan General Manager

DF/akg Attachment

cc: John A. Benson – Barton & Loguidice, P.C.



Ruston Paving Company, Inc.

6216 Thompson Road - Syracuse, New York 13206

Tel: (315) 437-2533 Fax: (315) 437-1775 www.rustonpaving.com

June 20, 2011

Metalico Aluminum Recovery, Inc. C/O: Burt Coleman 6223 Thompson Road Syracuse, New York 13206

Dear Mr. Coleman:

Re: CAMU Cover Repairs

I have completed the inspection of the asphalt cover on the CAMU area. I have found a few areas where the existing asphalt patches need to be cracked sealed and a few spots of vegetation growing along the joint between the concrete dolly apron and asphalt pavement. Vegetation along the slopes of the pavement have been treated and are not entering the CAMU cap area.

Repair Procedures:

Crack seal edges and existing asphalt patches.

Treat all vegetation with a non selective herbicide (Round-up).

All repairs were completed by June 24, 2011.

Should you have any questions or concerns, please contact me at (315) 437-2533.

Sincerely,

Ruston Paving Co. Inc.

Chris Laurin
Project Manager







